Problem Description: power to the ON/OFF switch, but no power to the control panel.

Possible cause to the problem: poor connection of wire(lead) Test/Solution proposed: as followings, suitable for all models.

